

Oil Field Environmental Incident Summary

Incident: 20150426110142

Date/Time of Notice: 04/26/2015 11:01

Responsible Party: ConocoPhillips Company

Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: CCU GOPHER CTB

Field Name: CORRAL CREEK

Well File #:

Date Incident: 4/25/2015

Time Incident: 12:25

Facility ID Number: 416647-17

County: DUNN

Twp: 147

Rng: 95

Sec: 15

Qtr: NW NW

Location Description: On well site

Submitted By: James Smith

Received By:

Contact Person: James Smith

PO BOX 51810

MIDLAND, TX 79710-1810

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	2	Barrels	2	Barrels		

Description of Other Released Contaminant:

Ruptured vibrator hose. This is the line that connects the mud pump to the Kelly hose on the rig.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

N/A

Potential Environmental Impacts:

None

Action Taken or Planned:

Immediately stopped operations and cleaned up spill. Review scheduled inspection and change out of vibrator and Kelly hoses.

Wastes Disposal Location: What can be recycled will go through mud system. All other waste will be mixed with cuttings and hauled to disposal facility.

Agencies Involved:

Updates

Date: 4/27/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.